



Made to Order Top Plate “Print Checklist”

- **3 or 4 decimal places on all dimensions**
- **Dimension off a corner** not a hole (preferably off the back left or front right corner)
- **Delete all base entities** shown
- Create **side view as needed** especially for Top Plates that are not standard thickness
- Guide Pin **connection holes** need to be **shown** and locations **dimensioned**
- **Reamed** holes need to be labeled for **fit** (press-slip) and **depth**
- If base screw **access holes** (wrench holes) are needed in the top plate, they need to be **shown** and **dimensioned**
(SM - .328 Drill / SL - .469 Drill)
- **Contours** need to be fully **dimensioned**
- If there is any entities that have a very tight tolerance please note the tolerance
- We would prefer the file be **sent** as a **.DXF** file type

We need to open the file, print it, send it to our CNC Milling department, with no additional information needed.